

BEST AVAILABLE COPY






FIG. 1



2ND FLOOR PLAN

FIG. 2

unchanged



3RD FLOOR PLAN

FIG. 3

*unchanged.*




Fig. 4




Fig. 5




Fig. 6

# Substructure





FIG. 1

# Interface Level

first tunnel walls  
second tunnel walls  
and poured-in-place  
concrete

an interface level comprising a plurality of  
adjacent, poured-in-place concrete


fourth tunnel walls  
vertically aligned with  
said second tunnel  
walls and having a  
fourth length



2ND FLOOR PLAN

# Superstructure

superstructure comprising a plurality of parallel adjacent, spaced in-place tunnels having [hatched pattern] that are each vertically aligned with one of said first and second tunnel walls.




3RD FLOOR PLAN

FIG. 3



Color-coded  
Schematic  
Corresponding to  
Figures 5 and 6



**This Page is Inserted by IFW Indexing and Scanning  
Operations and is not part of the Official Record**

**BEST AVAILABLE IMAGES**

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images include but are not limited to the items checked:

- ☐ BLACK BORDERS
- ☐ IMAGE CUT OFF AT TOP, BOTTOM OR SIDES
- ☐ FADED TEXT OR DRAWING
- ☐ BLURRED OR ILLEGIBLE TEXT OR DRAWING
- ☐ SKEWED/SLANTED IMAGES
- ☐ COLOR OR BLACK AND WHITE PHOTOGRAPHS
- ☐ GRAY SCALE DOCUMENTS
- ☐ LINES OR MARKS ON ORIGINAL DOCUMENT
- ☒ REFERENCE(S) OR EXHIBIT(S) SUBMITTED ARE POOR QUALITY
- ☐ OTHER: \_\_\_\_\_

**IMAGES ARE BEST AVAILABLE COPY.**

**As rescanning these documents will not correct the image problems checked, please do not report these problems to the IFW Image Problem Mailbox.**